Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5063**

Resource Identification

Property Name(s): ..... John Redd House (Redd Property) {Current}
Property Date: ..... ca 1910
Address(s): .... 12341 Old Suffolk Road {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story, 3-bay	Wood	Porch - Post, Square
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Vinyl Siding
Windows	Windows - Double-hung	Wood	Windows - 2/2
Chimneys	Chimneys - Interior end	Brick	Chimneys - Common Bond

Site Description: ..... This house is located in a rural area. John Redd, the owner of this house is the son of Mr. Redd who lives to the east.

Secondary Resource Desc: There are seven outbuldings that are associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
1	Garage	Historic
1	Storage	Historic
1	Shed	Historic
1	Dairy	Historic
1	Hay Barn	Historic
1	Equipment Shed	Historic
1	Barn	Historic

NR Resource Count:

Report generated 12/2/04

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5063**

Individual Resource Information

WUZIT: ..... Barn

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: To the northwest are a barn and an equipment shed. The barn and equipment shed feature weatherboard exteriors and roofs covered in standing-seam metal.

WUZIT: ..... Equipment Shed

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: To the northwest are a barn and an equipment shed. The barn and equipment shed feature weatherboard exteriors and roofs covered in standing-seam metal.

WUZIT: ..... Dairy

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The dairy house is constructed of corrugated metal and concrete block and displays a gabled roof covered in standing-seam metal.

WUZIT: ..... Shed

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The shed is also an open structure, but with a gabled roof clad in corrugated metal.

WUZIT: ..... Hay Barn

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: To the northeast of the house is a hay barn, dairy house, and a shed. The hay barn is an open structure with a gabled roof covered in standing-seam metal.

WUZIT: ..... Storage

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	2.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: North of the garage is a two-story storage shed that is entirely clad in corrugated metal with two brick chimneys situated in the interior portion of the roof.

WUZIT: ..... Garage

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: There are seven outbuildings associated with this house. Northeast of the house is a garage with a weatherboard exterior and gabled roof covered in standing-seam metal.

WUZIT: ..... House

Est. Date of Construction:	1910 ca {Site Visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	1.5
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built c. 1910, this one-and-one-half-story Frame Vernacular style house features a wooden frame structural system that rests on brick piers. The exterior of this house is covered in vinyl siding and the cross-gabled roof is clad in standing-seam metal. Fenestration consists of two-over-two wooden double-hung sash windows. There are three brick chimneys associated with this house. A chimney is located at each interior end of the house and the third chimney is located on the central interior portion of the roof in the rear. A hipped front porch is located on the south elevation and is supported by square wooden columns on concrete piers. The current owner of this house is another son of Mr. Redd (VDHR # 046-5058).

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Subsistence/Agriculture

Historic Time Period(s): ..... P- Reconstruction and Growth (1865 to 1914)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Reference #: 1

Bibliographic RecordType: ..... Survey

Author: ..... CCR, Inc.

Citation Abbreviation: .....

Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-5063**

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	9	VDHR	2004/07/01	Farm Complex

Cultural Resource Management (CRM) Events

CRM Event # 1,

Cultural Resource Management Event:	Phase I Survey
Date:	2004/08/31
Organization or Person:	CCR, Inc.
VDHR Project ID # Associated with Event: .	2002-1760
CRM Event Notes or Comments:	VDHR # 2002-1760 VDOT # 0460-969-101, PE-101 Architectural Survey, Route 460 Corridor Study

CRM Event # 2,

Cultural Resource Management Event:	DHR Staff: Not Eligible
Date:	2004/11/18
Organization or Person:	
VDHR Project ID # Associated with Event: ..	2002-1760
CRM Event Notes or Comments:	